



Critical review

Carbucks ApS

Bygholm Åvænget 4 C, 8700 Horsens

Collision Claims Vehicle Repair Service following the functional unit: *one (1) collision claims repair of an exterior body plane on a passenger vehicle, carried out at a Carbucks service location within a two-hour timeframe. 5 cases are included in the review with a worst-case scenario of 8,14 kg CO₂e and a best-case scenario of 6,59 kg CO₂e.*

Method: ISO 14067:2018

Object

The critical review has been conducted on the Product Carbon Footprint report "Carbucks PCF_Documentation Report_Round 2.3" version 30/09 2025. The reporting, modelling, and other relevant documents have been provided and review in relation to the listed standards.

Declaration

The review has been completed as a critical review with limited assurance by an external panel of reviewers. We hereby confirm that nothing has come to the reviewers' attention which would lead to conclude that the study does not give an accurate depiction or is not completed following the requirements of ISO 14067:2018, and 14071:2024, in the above referenced LCA report.

Ref.: "Carbucks_20250916_ISO 14067_Checklist_Round 2.3" 30/09 2025

Date of certificate: 30-09-2025

Expire date: 30-09-2027

Reviewed by: Waldemar Corydon Hemdrup, LCA & EPD Consultant, Lead reviewer

Reviewed by: Julie M.V. Larsen, LCA & EPD Consultant, Reviewer